

금속 소재의 환경노출거동: 9주차 Degradation Behavior of Metals and Alloys after Exposure to Elements: 9th Lecture

날짜: 2020년 10월 30일

■ 강의 내용

- 1. Nernst-Wagner method를 응용하여 전기 화학 전지의 캐소드를 결정하는 방법 ⇒ 다음의 그림들을 참조할 것.
- 보다 직관적으로 금속의 부식을 이해 할 목적으로 습한 분위기에 놓여 있는 철의 부식 거동을 밑의 그림을 참조하여 예측하고 이를 지중에 매설된 철 pipe의 부식 거동 예측에도 유사하게 적용한다.
- → Nernst-Wagner 법의 다양한 응용 예를 숙지한다.






cf. p. 2 위의 그림과 같은 산소 농도차 전지의 경우 어느 쪽에서 금속(Fe)의 부식이 일어날까?

-. 그림에서 0.2기압의 산소가 공급되는 백금 전극 표면에서 물이 산 화된다고 가정 함

$$OH^{-} \rightarrow \frac{1}{2}H_{2}O(l) + \frac{1}{4}O_{2}(0.2atm) + e^{-}(\alpha) - \bigcirc$$

그리고 오른쪽 백금전극에서 물이 환원된다고 가정

$$\frac{1}{2}H_2O(l) + \frac{1}{4}O_2(0.2atm) + e^-(\beta) \rightarrow OH^- - 2$$




① + ② 하면 양변에서 OH^- 와 $\frac{1}{2}H_2O$ 가 소거


$$\frac{1}{4}O_2(1atm) + e^-(\beta) = \frac{1}{4}O_2(0.2atm) + e^-(\alpha)$$

$$\begin{split} &-F(\varPhi^{\beta}-\varPhi^{\alpha})=\frac{1}{4}RTln\frac{0.2}{1}=\frac{1}{4}RTln0.2\\ &\varPhi^{\beta}-\varPhi^{\alpha}=-\frac{RT}{4F}ln0.2>0\,(\because-\ddot{\vdash}\,\ddot{\mathfrak{D}}\,) \end{split}$$


ightarrow 금속의 부식과 관련된 아주 중요한 결론으로 땅에 쇠파이프를 묻으면 산소의 농도가 희박한 흙속에 묻힌 부분이 밖에 노출된 부분보다 anodic ightarrow 부식된다. p. 1의 그림에서 보면 질소가 공급되는 철 전국에서, Fe^{2+} 이온 농도가 낮은 용액에 담겨있는 철 전국에서 산화 반응이 일어난다. ightarrow p. 3 맨 위의 그림도 참조 함.

2. 갈바닉 부식 및 갈바닉 부식에 미치는 실험변수의 영향






① 갈바닉 부식의 정의: 두 이종 금속이 밑의 그림과 같이 전기화학적으로 짝을 이루고 있음




-. 갈바닉 부식을 일으키는 전기화학 전지의 구성 요소:

anode, cathode, conductive path, electrolyte

-. 일단 전기 화학 전지를 고려 함. → 철 전극과 구리 전극을 각각 자신의 이온 1 M이 들어있는 용액에 담그면 철은 부식되고 구리는 전착 됨.



STANDARD EMF SERIES



Noble or


cathodic

-. 여기서도 Cd는 부식되고 Ni은 전착 됨

-. 이제 실제로 관찰되는 갈바닉 부식의 예와 예방책을 설명 함. Platinum Gold Graphite Titanium Silver Chlorimet 3 (62 Ni, 18 Cr. 18 Mo Hastelloy C (62 Ni, 17 Cr, 15 Mo) [18-8 Mo stainless steel (passive) 18-8 stainless steel (passive) Chromium stainless steel 11-30% Cr (passive) Inconel (passive) (80 Ni, 13 Cr. 7 Fe) Nickel (passive) Silver solder Monel (70 Ni, 30 Cu) Cupronickels (60-90 Cu, 40-10 Ni) Bronzes (Cu-Sn) Copper Brasses (Cu-Zn) Chlorimet 2 (66 Ni, 32 Mo, 1 Fe) Hastelloy B (60 Ni, 30 Mo, 6 Fe, 1 Mn) Inconel (active) Nickel (active) Tin Lead Lead-tin solders [18-8 Mo stainless steel (active) 18-8 stainless steel (active) Ni-Resist (high Ni cast iron) Chromium stainless steel, 13% Cr (active) Cast iron Steel or iron 2024 aluminum (4.5 Cu, 1.5 Mg, 0.6 Mn) Cadmium Commercially pure aluminum (1100) Magnesium and magnesium alloys

Active or


anodic



@ 구리/steel 접합



Copper rivets in steel plate Large anode Small cathode



Steel rivets in copper plate Large cathode Small anode


- -. 왼편의 경우 small cathode, large anode; 전반적으로 부식되었으나 접합은 단단히 유지 됨
- -. 오른편의 경우 large cathode, small anode로 전체적으로 구조물의 부식은 거의 없지만 접합부가 부식되어 구조물이 분해 됨.
- cf. 갈바닉 접촉을 이루는 두 이종 금속 중 하나를 페인트로 도포 하려면 cathodic metal (noble one)을 도포해야 함. Why?


reason = all paints/coating etc. are permeable to some degree and often contain inhomogeneities (cracks, scratches etc.)

If the anodic metal is coated – breaking of the coating results in small anodes forming cf. the large metal cathodes

:. corrosion = very rapid and severe

⑤ 자유의 여신상의 갈바닉 부식 손상 보수 (1986)







ⓒ Galvanic Series: 해수에 갈바닉 쌍이 담겨있고 두 금속이 전기적으로 접촉 시 어느 금속이 우선적으로 부식되고 어느 금속이 보호되는지 갈바닉 배열순서 (Galvanic Series, **p. 4의 우편**, p. 5의 위에 수록)로 부식 거동을 예측 가능 함.

@ Graphical examples of galvanic corrosion

Galvanic Corrosion



Galvanic corrosion of Magnesium insert in Iron shell



② 알바니 부식의 예방책과 실제 응용 예

Prevention Techniques

- selecting metals of similar electrode potentials to minimise the driving force of the process
- protection against moisture condensation to eliminate the chance of forming an electrolyte
- · insulation between dissimilar metals to avoid electrical connection
- · coating for electrical insulation or isolation of metal from electrolyte
- · installing a third metal which is anodic to both metals
- designing for easy replacement of the anode metal or thicker section for longer service life

Beneficial Applications of Galvanic Corrosion

- Cathodic protection, sacrificial anode protection
 Galvanised steels: Zn coating is anodic to steel, act as a sacrificial metal
- · Cleaning silver

blackened surfaces: silver sulphide

rubbing with an abrasive? bad for silver plates

Ag in Al pan: soda solution:

cathodic reaction reduces silver sulphide to Ag

② 갈바닉 부식에 미치는 실험변수의 영향

e.g. sometimes - cathode/anode combination can reverse

@ 환경 요인

e.g. steel and zinc in galvanic combination

(매우 중요함) - zinc will corrode and steel remains inert (basis of sacrificial anodes)

BUT/

if temperature is greater than 83°C or if nitrates/carbonates are present in water:

- steel will corrode and the zinc passivates

Atmospheric galvanic corrosion? Depends on moisture content

e.g. 2 cars- 1 parked in Canberra 1 parked in coastal Sydney

Coastal car corrodes much faster a) more humid

If the atmosphere is completely $dry-galvanic\ corrosion\ doesn't\ occur$

b) salt in the air

- 8 -

(b) 접합으로부터의 거리

Effect of distance

corrosion effects are greatest nearest 'junction'


– where 2 metals meet

breadth of corrosion – increases with increasing solution conductivity could also be a sharp groove at the intersection.... why?

because of corrosion rates and mass removal i.e. current density effects

③ 예방책: 두 이종금속을 전기적으로 절연시킴

Corrosion Prevention - Dissimilar Metal Joint



④ Area Effect의 정량적 계산

-. Cu-Zn corrosion couple: p. 736 of "The Science and Engineering of Materials" by Donald R. Askeland, Third Ed.